



ESAP

Release Notes

Release, Build	3.5.8
Published	March 2020
Document Version	1.0

Pulse Secure, LLC

2700 Zanker Road, Suite 200

San Jose, CA 95134 <https://www.pulsesecure.net>

© 2020 by Pulse Secure, LLC. All rights reserved

Pulse Secure and the Pulse Secure logo are trademarks of Pulse Secure, LLC in the United States. All other trademarks, service marks, registered trademarks, or registered service marks are the property of their respective owners.

Pulse Secure, LLC assumes no responsibility for any inaccuracies in this document. Pulse Secure, LLC reserves the right to change, modify, transfer, or otherwise revise this publication without notice.

The information in this document is current as of the date on the title page.

END USER LICENSE AGREEMENT

The Pulse Secure product that is the subject of this technical documentation consists of (or is intended for use with) Pulse Secure software. Use of such software is subject to the terms and conditions of the End User License Agreement ("EULA") posted at <https://www.pulsesecure.net/support/eula>. By downloading, installing or using such software, you agree to the terms and conditions of that EULA.

Contents


Introduction.....	4
Interoperability and Supported Platforms	4
Noteworthy Changes.....	4
ESAP 3.5.8 and Pulse Connect Secure/Pulse Policy Secure Compatibility Chart	5
V4 List of Supported Products	5
Fixed Issues in ESAP 3.5.8.....	6
Known Issues/Limitations in ESAP3.5.8.....	6
Documentation.....	7
DocumentationFeedback.....	7
Technical Support.....	7
Revision History	7

Introduction

V3 SDK Version: Mac and Windows 3.6.11667.2

V4 SDK Version: Windows 4.3.1182.0, Mac 4.3.1090.0

V3V4 Adapter Version: Windows 4.3.828.0, Mac 4.3.814.0

 Note: The SDK embedded in this ESAP version has been tested and qualified to interoperate with an extensive list of endpoint security applications covering most products listed in the supported products list.

Interoperability and Supported Platforms

Please refer to the [ESAP Supported Platforms Guide](#) for supported versions of browsers and operating systems in this release.

Noteworthy Changes

- Pulse Secure introduced support for consuming the latest OPSWAT SDK Version 4 in 8.2R5 PCS and PPS 5.3 R5 PPS release.
 - OPSWAT SDK's are bundled within our Endpoint Security Assessment Plugin (ESAP). From ESAP 3.0.3 onwards, OPSWAT V4 SDK for Windows and Mac are packaged alongside existing V2 and V3 SDKs.
 - Uploading ESAP 3.0.3 or Later on PCS 8.2R4 and below or PPS 5.3R4 and below release will continue to install and leverage the older Version 2 and Version 3 OPSWAT SDKs. There will be no change in the functionality/usage on PCS 8.2R4 / PPS 5.3R4 and below release versions.
 - Uploading ESAP 3.0.3 or later on PCS 8.2R5 PCS or PPS 5.3R5 releases, we will install OPSWAT V4 SDK version along with V2 and V3 SDKs.
 - On the PCS 8.2R5 and PPS 5.3R5 Admin UI, Administrators have a choice to select whether OPSWAT V3 or V4 SDK will be consumed on the device running PCS 8.2R5 or PPS 5.3R5. Please refer to the section "Activating the OPSWAT SDK Version" in the PCS 8.2R5 and PPS 5.3R5 Administration Guide available on [Techpubs](#) website for more information.
 - Endpoint Security Assessment Plug-In (ESAP) provides support for predefined checks on Windows and MAC platforms. ESAP package contains V2, V3 and V4 OPSWAT SDK versions. Support for V2 and V3 OPSWAT SDK is ended. Hence, this ESAP release has only OPSWAT V4 version updated in ESAP package. Refer to KB article http://kb.pulsesecure.net/articles/Pulse_Technical_Bulletin/TSB41055 on Pulse Secure site for more details.

ESAP 3.5.8 and Pulse Connect Secure/Pulse Policy Secure Compatibility Chart

This ESAP package can be installed on the following Pulse Connect Secure/ Pulse Policy Secure software versions.

- PCS 9.1RX
- PCS 9.0RX
- PCS 8.3Rx
- PCS 8.2Rx
- PCS 8.1Rx
- PPS 9.1RX
- PPS 9.0RX
- PPS 5.4Rx
- PPS 5.3Rx
- PPS 5.2Rx
- PPS 5.1Rx

 Note:

- The ESAP package may install and function without any errors on older releases. However, as the install has not been tested, we recommend that it be used only on the above versions of software releases.
- This ESAP package contains V3 and V4 versions of OPSWAT SDK. From the above compatibility chart V4 is applicable only for release above 8.2R5 and 5.3R5.

Support Has Been Added for the Following Products in ESAP 3.5.8

V4 List of Supported Products

Windows OS

Antivirus Products

- Traps (7.x)

Antispyware Products

- Traps (7.x)

macOS

Antivirus Products

- Norton 360 (8.x)
- Traps (7.x)

Antispyware Products

- Norton 360 (8.x)
- Traps (7.x)

Fixed Issues in ESAP 3.5.8

The following table lists Fixed issues in ESAP3.5.8

Problem Report Number	Summary
PRS-388158	Summary: Host Checker : Need to add support for Traps 7.x for Windows and Mac.
PRS-388426	Summary: Carbon Black Defense Sensor 3.5.0.1523 fails RTP check

Known Issues/Limitations in ESAP3.5.8

The following table lists known issues/limitations in ESAP3.5.8

Problem Report Number	Release Note
OPSWAT	
958840, 845980	Remediation of Windows Firewall 8 in agentless mode requires administrative privileges and UAC should be turned off.
502783	Endpoint Protection 11.x/12.x is not performed when UAC is enabled or if the scan logs have been deleted or if system scans has never been performed.
495041	The password protection option in the Sunbelt Kerio Firewall product is not supported.
	Remediation and detection of Windows Firewall 7 and Vista in agentless mode requires administrative privileges and UAC to be turned off.
	For Symantec, Hosted Endpoint Protection 2.x installed on server operating systems, GetLastFullSystemScanTime function will return either the last full system scan time or last quick system scan time. Server operating systems include, Server 2008, Server 2008 R2, Server 2003 and XP x64.
785223	FSRTP status for avast! Free Antivirus 7.x will not be detected until user manually configures FSRTP status at least once. That is, user should turn off "File System Shield" and turn it on.
950123	Signatures cannot be downloaded with Trend Micro Office scan Client 10.5 and 10.6. Therefore, the remediation functionality for failing the virus definition check is not supported for Trend Micro Office scan Client 10.5 and 10.6. This is because the executable required to support this functionality is not bundled as part of the TrendMicro product.
PRS-357241	Hostchecker is failing to detect Bitlocker HD encryption 10.x in Windows 10 via browser, but detects with Pulse

Problem Report Number	Release Note
PRS-380100	Host Checker stopped working after Upgrading ESAP from 3.3.5 to 3.4.4 or 3.4.5 in Mac OS Mojave 10.14.5 and 10.14.6.

Documentation

Pulse documentation is available at <https://www.pulsesecure.net/techpubs/>

Documentation Feedback

We encourage you to provide feedback, comments, and suggestions so that we can improve the documentation. You can send your comments to techpubs-comments@pulsesecure.net.

Technical Support

When you need additional information or assistance, you can contact "Pulse Secure Global Support Center (PSGSC):

- <https://www.pulsesecure.net/support>
- support@pulsesecure.net
- Call us at 1- 844-751-7629 (toll-free USA)

For more technical support resources, browse the support website <https://www.pulsesecure.net/support>

Revision History

The following table lists the revision history for this document.

Revision	Date	Description
1.0	March 2020	Initial Publication